

CAUTION

READ CAREFULLY BEFORE STARTING PLANT

STARTING PROCEDURES FOR ALL ASPHALT PLANTS , CRUSHER PLANTS AND OTHER PIECES OF EQUIPMENT CONNECTED WITH THE PLANTS.

PROCEDURES ARE AS FOLLOWS:

1. VISUAL CONTACT MUST BE MADE BY PLANT OPERATOR WITH ALL PLANT PERSONNEL PREVIOUS TO STARTING PLANT FOR OPERATION.

2. DURING HOT SHUTDOWN THE SAME PROCEDURE WILL BE FOLLOWED.

3. PLANT COMMUNICATIONS

A. VISUAL CONTACT

B. RADIO COMMUNICATION

C. PLANT WARNING HORN

ALL THREE MUST BE USED DURING PLANT OPERATION.

4. LOCKOUT PROCEDURES

OTHER THAN NORMAL MAINTENANCE

ALL SYSTEMS WILL BE SECURED BY LOCKS
WHERE POSSIBLE

ALL HYDRAULIC, PNEUMATIC, ELECTRICAL
AND MECHANICAL SYSTEMS WILL BE
SECURED.

FAILURE TO ADHERE TO THESE POLICIES
WILL GIVE CAUSE FOR DISCIPLINARY
ACTION